

: Multiple Choice


The Machine shown in the figure and number of Axis is:

- a CNC lathe machine – 2Axis
- b CNC mill machine – 3Axis
- c CNC grinding machine – 3Axis
- d CNC drilling machine – 2Axis



The Machine shown in the figure and number of Axis is

- a CNC lathe machine – 2Axis
- b CNC mill machine – 3Axis
- c CNC grinding machine – 3Axis
- d CNC drilling machine – 2Axis



Stops all operations when its pressed.

- a Spindle.
- b Emergency Button.
- c Y- Axis Stepper Motor.
- d Z- Axis Stepper Motor.