

Micrometer Measurements (1)

For each of the pictures shown below, enter the correct measurement in the box provided.



mm



mm



mm



mm



mm



mm

In all of these measurements, we have assumed that the micrometer read exactly zero when it was fully closed. Although micrometers can be adjusted to give a true zero reading, sometimes there is a small error that needs to be taken into account. To test your understanding of zero errors, you should attempt Micrometer Measurements (2).