



Check your understanding

True or false:

Isometric drawings are a very commonly used form of pictorial drawing	
In isometric drawings, all vertical lines remain vertical while horizontal lines project at 30° to the left or 45° to the right.	
In CAD, the standard 3D view on the screen is usually oblique.	