

HOW TO TURN OFF THE COMPUTER

CLICK ON THE START BUTTON		STEP 1
WINDOWS IS SHUTTING DOWN		STEP 2
SWITCH OFF THE UPS BUTTON		STEP 3
SWITCH OFF THE MAIN POWER SUPPLY BUTTON		STEP 4
CLICK ON THE SHUTDOWN OPTION		STEP 5
CLICK ON THE POWER BUTTON		STEP 6