

## Eye Protection

| Goggles                                                                             | Name | Used for |
|-------------------------------------------------------------------------------------|------|----------|
|    |      |          |
|    |      |          |
|   |      |          |
|  |      |          |

Shaded Safety goggles

Clear Safety goggles

Welding Safety goggles

Grinding Safety goggles

Use when brazing and light duty gas welding and cutting work. Not for arc welding.

The filter shade glass are mounted in a flip-up front frame. Protection glass must be placed in front of the filter shade glass.

Use during daily maintenance work in workshop and on site for protection against flying objects.

Half mask goggle of clear soft synthetic none-mist material. For grinding only.